

## **Notice to Mariners**

## Beatrice Offshore Windfarm Limited (BOWL) - Notice to Mariners March 2018.

## **Cardinal Mark off Station**

Date of Issue   11 <sup>th</sup> March 2018   Notice Number   LF000005-NTM-041-Rev02
--

Please promulgate the following as a Notice to Mariners:

The following Aid to Navigation broke free of its mooring and drifted off station.

Name	Coordinates (WGS84)	Characteristics
Beatrice OWF, West Cardinal Mark	58° 12.56'N 003° 01.32'W	West Cardinal shaped top mark, VQ(9) 10s light and AIS




Fig 1 Location of the Beatrice OWF, West Cardinal Mark

The Cardinal Mark has been recovered and will be returned to station as soon as possible.

During the period that the Buoy is off station a Navigational Warning **WZ 310/**18 has been issued by the UKHO. This will be broadcast 6 times a day by NAVTEX and twice a day by voice on VHF radio.

The remaining anchor chain of the West Cardinal Buoy has been located and an orange Norwegian buoy attached in position 58° 12.56'N 003° 01.32'W, as shown on the picture below. This buoy will remain in place until the West Cardinal mark is reinstated.

LF000005-NTM-041 Rev 02 Notice to Mariners West Cardinal Mark off station





Any questions regarding this Notice to Mariners should be directed to Beatrice Offshore Wind Farm Marine Coordination office.

## Notice issued by:

BOWL Marine Coordinator
Beatrice Offshore Windfarm Limited
Unit 1
Harbour Office
Wick
Caithness
KW1 5HA

email: mc.bowl@sse.com phone: +44 (0) 3302020329 Mob: +44 (0) 7432 028 207 web site: www.sse.com/beatrice